

US 24 Alignment west of 31st Street

Recommendation: Align US 24 to the south

Factors that led to this recommendation: Engineering challenges of retaining walls and structures over the Fountain Creek
Property Impacts and land use

Who helped reach this recommendation: 06/25/08: Executive and Technical Leadership Teams endorsed this decision
05/16/08: Executive and Technical Leadership Teams briefing
03/26/08: Meeting with Safeway Stores, Inc., to discuss its development plans
Multiple meetings with property owners (business and residential)