


Burlington Rest Area - I-25 MM 437.6
Elevation \approx 4170'

CDOT Region #4



Summary Observations

An on-site ADA survey was conducted September 1, 2016, by Patrick Going, ADA Consultant. All observations are based on the 2010 ADA Standards for Accessible Design. These Standards may be found at www.access-board.gov.

This rest area is housed with a Colorado Welcome Center. It has been remodeled recently and is exceptionally clean, well lit, and well landscaped. It is located 13 miles from the Kansas border and **is only available west bound.**

Parking

There are two car parking areas **with 52 total spaces.** The area on north side has 40 parking spaces, with no accessible spaces, and the area on the west side has 12 parking spaces with 6 accessible spaces. One of the accessible parking spaces is identified as ‘van.’ **A helpful sign at the rest area entrance directs people to the accessible parking location.**

There is a separate parking areas for RV’s and trucks. Although there is not a designated accessible parking space for trucks or RVs, an accessible path to the building is provided.

Path-of-Travel

The route from the current accessible car parking spaces to the building is acceptable with the exception that the landing area at the entrance door on west side of building is not 60” x 60”. See picture.



Rest Rooms

All the restrooms comply fully with the ADA Standards.

Vending Machines, Visitor Information, and Other Amenities

All outside information signs and indoor services are accessible in conjunction with the Colorado Visitor Center. Wi-Fi is available.

Dog Relief Areas

There are numerous ‘dog relief’ areas available - though not formally designated. Most are accessible for people with assistive mobility devices.

ADA Graded Summary*

Based on 2010 ADA Standards for Accessible Design



Excellent



Moderate



Poor

Parking 	Path-of-Travel to Building/Services 	Restrooms 	Vending/Picnic Tables 
52 spaces/6 accessible including one 'van.'	Paved surface, good curb cuts. Landing at the west entrance is not 60" x 60".	Women's - ADA compliant Men's - ADA compliant	Pet area available Vending machines & picnic tables accessible.

Recommendations	
Description	Priority
Expand the landing at the west entrance to a full 60" x 60".	Soon





Clean, fully compliant ADA restrooms



Path of travel from RV/Truck parking area.

