

Genessee Buffalo Herd/Pull-Out - I-70 MM 254
Elevation \approx 7650'

CDOT Region #1



Summary Observations

An on-site ADA survey was conducted September 27, 2016, by Patrick Going, ADA Consultant. All observations are based on the *2010 ADA Standards for Accessible Design*. These Standards may be found at www.access-board.gov.

This rest area serves several functions. It is a ‘park & ride’ lot for commuters to the Denver Metro area as well as a parking lot for viewing the buffalo herd. It does provide a safe stopping point for travelers to rest and stretch. It offers no amenities other than a paved parking lot and an opportunity to view the buffalo most times of the year.

Parking

There are 20 parking spaces with one designated accessible parking spot with a vertical sign and access aisle. This lot is not designed for trucks or large RVs.

Path-of-Travel

The path from the open parking to the visitor sign and overlook is not accessible for a person using a wheelchair. The path to the viewing fence is gravel/dirt.

Rest Rooms

There are no restrooms.

Vending Machines and Visitor Information

There are no vending machines or information signs.

Dog Relief Areas

There are numerous ‘dog relief’ areas. Most are accessible for people with assistive mobility devices.

ADA Graded Summary*

*Based on 2010 Standards for Accessible Design



Excellent



Moderate



Poor

Parking 	Path-of-Travel to Viewing Area 	Restrooms N/A	Vending/Picnic Tables N/A
20 car parking spaces with 1 Accessible Space. Surface is paved.	Gravel path from road to fence.	None Provided	None Provided

Recommendations

Description	Priority
ADA requires at least one van accessible parking space (§208.2.4). Expand existing access aisle to 8' wide to accommodate vans or cars.	Soon
Raise accessible parking sign to 60"	Immediate



