ROADWAY AND BRIDGE CONDITIONS AND DEFICIENCIES *(Peyton to Calhan Segment)*

Peyton Hwy
McClelland Rd
Ellicott Hwy
Kobilan Rd
Soapweed Rd
Eurich Rd
Calhan Hwy
Murphy Rd
Smith Ranch Rd
Log Rd
Peyton
Calhan
Calhan Airport
El Paso County Fairgrounds
Fairplay Rd
Mc Clelland Rd
Guthrie Rd
Scott Rd
30
31
333
334
24
335
338
339
340

Uncontrolled access to private properties on all corners of intersection of Yoder St and US 24

Passing/climbing lane with insufficient outside shoulder

Private property access directly on southeast corner of the intersection of US 24 and Ellicott Hwy

LEGEND

- Peyton to Calhan Segment
- County Boundary
- City Boundary
- Parks and Open Space
- Major Streams
- Airport
- US 24 Milepost

Structural Deficiencies

- Functionally Obsolete or Structurally Deficient
- Failing Permit Load Rating
- Potential Minor Repairs Recommended (15-Year Horizon)

Potential Deficiencies

- Potential Clear Zone Deficiency
- Potentially Insufficient Radius for Design Speed
- Potential Guardrail Deficiency
- Areas with Other Potential Deficiency

0 0.5 1 Miles

NORTH